



FIN: WDD 213033 1A 173628

Current advice for the vehicle:

none

Outstanding KDM:

Damage code	Description	End date	Campaign state	KDM-Type	Days to Expire
1590007	20P1590007		Active	Recall	0
5497423	21P5497423		Active	Recall	0
5499014	22P5499014		Active	Service-Campaign	0
5496116	18P5496116		Active	Service-Campaign	0

ESKULAB decisions:

Damage history:

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	08.07.2020				Service major	13399	RO W	52602	201378	km			
	03.04.2020				Service major	11731	RO W	52602	185959	km			
	30.11.2019				Service major - Mileage exceeded	1-01-882	D	02738	169662	km			
	29.11.2019		18	054961427	19P5496142	88202	D	02738	169662	km	0	000000000	13.12.2019
	29.11.2019	AA	17	08204X018	Map data update, navigation system Follow-up operations	88203	D	02738	169662	km	0	000000000	13.12.2019
	01.06.2019	AA	16	08204X018	Map data update, navigation system Follow-up operations	192785	D	02738	142551	km	0	000000000	14.06.2019
	01.06.2019				Service minor - Mileage exceeded	AU192785	D	02738	142551	km			
	30.11.2018		15	009334737	Boost pressure sensor Electrical fault	185952	D	02738	108982	km	0	000000000	14.12.2018
	30.11.2018	AB	14	014136077	Exhaust manifold, right Torn/cracked	185952	D	02738	108982	km	0	000000000	14.12.2018
	30.11.2018	AB	13	014136M18	Exhaust manifold, right Replacement vehicle, repair scope > 24 WU	185952	D	02738	108982	km	0	000000000	14.12.2018
	30.11.2018				Service major - Mileage exceeded	185952	D	02738	108982	km			
	28.08.2018	AC	12	087100EP7	Head unit Audio cuts out intermittently	183936	D	02738	95112	km	0	000000000	31.08.2018
	28.08.2018	AC	11	087100M18	Head unit Replacement vehicle, repair scope > 24 WU	183936	D	02738	95112	km	0	000000000	31.08.2018
	30.05.2018		10	020941428	\$1711P20D10 10 Remove plastic lug on fan unit housing	182646	D	02738	82753	km	0	000000000	15.06.2018
	30.05.2018		9	08210NEP8	Function, radio, AM/FM/HD, head unit Audio cuts out intermittently	182646	D	02738	82753	km	0	000000000	15.06.2018
	30.05.2018		8	068021067	Glove compartment Broken	182646	D	02738	82753	km	0	000000000	15.06.2018
	30.05.2018		7	06804C097	Trim piece, cover, center console Surface damage	182646	D	02738	82753	km	0	000000000	15.06.2018

**Vehicle Information (Damage history)**

52604

Type	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	30.05.2018		6	054W11908	Radar sensor, right, outer, bumper, front Software status	182646	D	02738	82753	km	0	000000000	15.06.2018
	30.05.2018		5	043700908	Function, lane monitoring Software status	182646	D	02738	82753	km	0	000000000	15.06.2018
	03.11.2017		4	054987018	\$1705P54B05 10 Update engine control unit software	174722	D	02738	51040	km	0	000000000	01.12.2017
	03.11.2017		3	082557528	Amplifier, sound system Does not operate correctly	174722	D	02738	51040	km	0	000000000	01.12.2017
	03.11.2017				Service major - Regular service - Mileage exceeded	174722	D	02738	51035	km			
	13.04.2017		2	0598DM747	K/Z* M, control unit, diesel engine Contact fault/open circuit	171531	D	02738	19628	km	0	000000000	28.04.2017
	13.04.2017		1	042101H47	Brake disc, front Jerks	171531	D	02738	19628	km	0	000000000	28.04.2017
	12.04.2017				Service minor - Regular service	171531	D	02738	19618	km			